

# Acceptance Sampling and Its Application to Visual Inspection of Injectable Products

John G. Shabushnig, Ph.D. Insight Pharma Consulting, LLC



johnshabushnig@aol.com March 2018



#### How Do We Inspect?

- 100% inspection
  - Manual Inspection
  - Automated Inspection
- Acceptance Sampling



#### Sampling vs. 100% Inspection

- Sampling preferred when:
  - Test is destructive
  - Test cost is high
  - Lot size is very large
- 100% Inspection preferred:
  - To remove low numbers of randomly distributed defects
  - When risk of a defective unit is high



- Acceptance Sampling
  - Inspection of a sample from a lot to decide whether to accept the lot.
- Lot Size (N)
  - The total number of items to be considered together for acceptance or rejection.
- Sample Size (n)
  - The number of items selected at random from the lot for testing or inspection.



- Acceptable Quality Limit (AQL)
  - The defect level that will be routinely accepted by the sampling plan. 95% of the time, lots of this quality will be accepted. Defines the producer's risk.
- Unacceptable Quality Limit (UQL) or Lot Total Percent Defective (LTPD)
  - The defect level that will be routinely rejected by the sampling plan. 90% of the time, lots of this quality will be rejected. Defines the customer's (patient's) risk.


5



- Operating Characteristic (OC) Curve
  - A plot of the probability of accepting a lot (y-axis)
     versus the lot percent defective (x-axis). This curve is descriptive of the protection provided by a given sampling plan.



#### Ideal Operating Characteristic Curve




AQL = 1.0%

UQL = 1.0%



#### **Operating Characteristic Curve**



**Single** 

N = 50,000

n = 315

a = 6

AQL = 1.1%

UQL = 3.3%



#### Sampling Plan

- Defined by the sample size (n) and the accept number (a) for a given lot size (N). Performance is shown by the operating characteristic curve and values for AQL and LTPD.
- Accept (a)/Reject (r) Number
  - When the sample contains defectives <= the accept for the sampling plan, the lot should be accepted. When the sample contains defectives >= to the reject number it should be rejected.



#### Single Sampling Plan


 Sampling inspection in which the decision to accept or reject a lot is based on the inspection of a single sample.

#### Double Sampling Plan

 Sampling inspection in which the inspection of the first sample leads to a decision to accept the lot, reject it or take a second sample. The inspection of the second sample, when required, then leads to a decision to accept or reject the lot.



## Single vs. Double Sampling Plan



**Single** 

n = 315

a = 6

**Double** 

n1 = 124

a1 = 1

n2 = 296

r1 = 6

a2 = 7


N = 50,000

AQL = 1.1%

UQL = 3.3%




#### **Switching Rules**





# Effect of Sample Size (n)




**Single** 

N = 50,000

AQL = 1.1%



# Effect of Lot Size (N)



**Single** 

n = 315


a = 6

AQL = 1.1%

UQL = 3.3%



#### Effect of AQL



**Single** 

N = 50,000

n = 315



# Standard Sampling Plans

- Mil Std 105e "Sampling Procedures and Tables for Inspection by Attributes"
  - Discontinued in 1991
- ANSI/ASQ Z1.4-2003 (R2013) "Sampling Procedures and Tables for Inspection by Attributes"
  - ISO 2859-1:1999
  - JIS Z 9015-1:2006
- Dodge-Romig
  - Average Outgoing Quality Limit (AOQL)
- Mil Std 1916
  - Zero accept plans




# Sampling Plans

	2014	2008	2003	1996
ANSI/ASQ Z1.4	65%	53%	70%	90%
ISO 2859	23%	11%	10%	0%
JIS Z9015	<b>7</b> %	15%	5%	0%
Mil Std 1916	3%	11%	0%	0%
Dodge Romig	1%	0%	5%	0%
Other	2%	10%	0%	10%



# What AQL value (in %) do you use for acceptance sampling of these defect categories?






# **ANSI Z1.4 Sampling Table**

			Special inspection levels			General inspection levels			
Lot or batch size			S-1	5-2	S-3	5-4	ı	"	111
2	to .	8	A .	٨	٨	٨	۸	٨	В
9	to	15	A	. <b>A</b>	٨	٨	٨	В	С
16	to	25	^	٨	В	В	В.,	С	D
26	to	50	^	В	. в	С	С	D	Е
51	to	90	В	В	С	С	С	E	F
91	to	150 ·	В	Ð	С	D	D	F	G
151	to	280	8	c	n	E	E	G	11
281	to	500	B	С	D	ε	F	11	,
501	to	1200	С	С	Е	F	G	J	к
1201	to	3200	c	Ð	Е	G	н	к	ւ
3201	to	10000	c	b	F	G	. ,	L	м
10001	to	35000	С	Ð	F	11	К	М	N
35001	to	150000	D	ε	G	J	ι	N	Р
150001	to	500000	b	3	G	J	М	P	Q
500001	and	over	D	£	11	ĸ	N	- Q	R



### **ANSI Z1.4 Sampling Table**



Use first sampling plan below arrow. If sample size equals, or exceeds, lot or batch size, do 100 percent inspection.

- Use first sampling ples above arrow.

Ac Acceptance number

le 💻 Rejection number.



#### Sample Collection

- Random
- Stratified
  - Subgroups
- Periodic
  - Simple procedure
  - Easy to automate



#### How should a sampling plan be used?

- As a Safety Net
  - 100% inspection is not 100% effective
  - To detect new defect types with automated systems
  - To detect a process shift
    - Manufacturing or Inspection process




# What should you do when you exceed the Accept Number?

- Investigate (Always)
  - Inspection Process
  - Manufacturing Process
- Reinspect (Sometimes)
  - When it is appropriate (based on investigation)
- Reject Lot (Sometimes)
  - When reinspection is not successful



# **Any Questions?**



An Introduction to Visual Inspection © 2018 John G. Shabushnig