

## Training Course Agenda

PDA 293 Essentials Workshop - Contamination Control Strategy

DAY 1	
8:30	Welcome and Introductions
8:45	PDA Technical Report No. 90
9:00	Contamination Control Strategy – Foundation & Controls
10:30	Break
10:45	Contamination Control Strategy – Validation & Measures
12:00	Lunch
13:00	Contamination Control Strategy – Goverance & Feedback
14:30	Break
14:45	Contamination Control Strategy – Case Study
16:00	End of Training Course